

APPENDIX D
Hazardous Materials Notification Forms

HAZARDOUS MATERIALS NOTIFICATION FORM

PROJECT #: NCPD-PE02(910) STATION/SITE: A

MUNICIPALITY OR COMMUNITY: Browns, AL COUNTY: Dallas

FACILITY NAME: Bob and Bonnie's

FACILITY ADDRESS: U.S. Highway 80

Browns, AL 36724

OWNER'S NAME: NA

OWNER'S ADDRESS: U.S. Highway 80

Browns, AL 36724

FACILITY PHONE #: NA OWNER'S PHONE #: NA

ADEM REGISTRATION #: Site I.D. 4920

TYPE OF FACILITY [check applicable response(s)]:

- Gas Station
- Dry Cleaner
- Fertilizer Plant
- Plating Plant
- Leather Tannery
- Scrap Metal
- Chemical Plant
- Wood Treating Plant
- Auto Parts w/Engine Repair Shop
- Foundry
- Manufacturing Facility
- Farmer's Cooperative
- Landfill
- Other (Specify): UST Site

COMMENTS: Site identified from ADEM's list of Regulated USTs. Database indicates there are no USTs remaining on the site.

INSPECTOR'S NAME: _____

DATE INSPECTED: _____

SUPERVISOR'S SIGNATURE: _____

HAZARDOUS MATERIALS NOTIFICATION FORM

PROJECT #: NCPD-PE02(910) STATION/SITE: B

MUNICIPALITY OR COMMUNITY: Jones, AL COUNTY: Dallas

FACILITY NAME: Burnsville Country Store

FACILITY ADDRESS: 8890 Alabama Hwy 14 East

Selma, AL 36701

OWNER'S NAME: Ronnie & Ruth Mull

OWNER'S ADDRESS: 8890 Alabama Hwy 14 East

Selma, AL 36701

FACILITY PHONE #: (334)-872-5912 OWNER'S PHONE #: _____

ADEM REGISTRATION #: 22033-047-00461

TYPE OF FACILITY [check applicable response(s)]:

- Gas Station
- Dry Cleaner
- Fertilizer Plant
- Plating Plant
- Leather Tannery
- Scrap Metal
- Chemical Plant
- Wood Treating Plant
- Auto Parts w/Engine Repair Shop
- Foundry
- Manufacturing Facility
- Farmer's Cooperative
- Landfill
- Other (Specify): _____

COMMENTS: One pump island containing three pumps is located on the property. Four USTs were noted at the facility with three USTs on the west corner of the building and one UST on the east side of the building. The station sells regular and mid-grade gasoline as well as diesel.

INSPECTOR'S NAME: Jake Lambert

DATE INSPECTED: May 16, 2006

SUPERVISOR'S SIGNATURE: _____



Photo 1: View facing west of Burnsville Country Store. Pump island on the right side of the picture. Tank pit also seen on the right side of the photo.



Photo 2: View of diesel UST pit. Photo taken facing west along Alabama Hwy 14.

HAZARDOUS MATERIALS NOTIFICATION FORM

PROJECT #: NCPD-PE02(910) STATION/SITE: C

MUNICIPALITY OR COMMUNITY: Selma, AL COUNTY: Dallas

FACILITY NAME: Junction Parts and Service

FACILITY ADDRESS: 12687 U.S. Highway 80

Selma, AL 36701

OWNER'S NAME: NA

OWNER'S ADDRESS: 12687 U.S. Highway 80

Browns, AL 36701

FACILITY PHONE #: (334) 872-4002 OWNER'S PHONE #: _____

ADEM REGISTRATION #: Site I.D. 18254

TYPE OF FACILITY [check applicable response(s)]:

- Gas Station
- Dry Cleaner
- Fertilizer Plant
- Plating Plant
- Leather Tannery
- Scrap Metal
- Chemical Plant
- Wood Treating Plant
- Auto Parts w/Engine Repair Shop
- Foundry
- Manufacturing Facility
- Farmer's Cooperative
- Landfill
- Other (Specify): UST Site

COMMENTS: Site identified from ADEM's list of Regulated USTs. Database indicates there are no USTs remaining on the site.

INSPECTOR'S NAME: _____

DATE INSPECTED: _____

SUPERVISOR'S SIGNATURE: _____

HAZARDOUS MATERIALS NOTIFICATION FORM

PROJECT #: NCPD-PE02(910) STATION/SITE: D

MUNICIPALITY OR COMMUNITY: Selma, AL COUNTY: Dallas

FACILITY NAME: PJ's Party Store

FACILITY ADDRESS: 9815 Highway 22

Selma, AL 36701

OWNER'S NAME: L.C. Pettaway

OWNER'S ADDRESS: P.O. Box 592

Selma, AL 36701

FACILITY PHONE #: NA OWNER'S PHONE #: 334-872-6272

ADEM REGISTRATION #: Record No. 6580

TYPE OF FACILITY [check applicable response(s)]:

- Gas Station
- Dry Cleaner
- Fertilizer Plant
- Plating Plant
- Leather Tannery
- Scrap Metal
- Chemical Plant
- Wood Treating Plant
- Auto Parts w/Engine Repair Shop
- Foundry
- Manufacturing Facility
- Farmer's Cooperative
- Landfill
- Other (Specify): LUST Corrective Action Site

COMMENTS: Site identified from ADEM's list of Corrective Action Sites. Mr. Lynn Ford (334-279-3054) with ADEM HAZMAT Section was contacted on 2-5-07 regarding the status of the Corrective Action Site. Mr. Ford said this is a LUST Site with LUST Incident No. 00-08-25. Mr. Ford said Mr. John Pierce (334-271-7792) in the ADEM Groundwater Section would have more up to date information on the status of the site. Mr. Pierce was contacted and provided the following information. A Closure Assessment has been conducted on the site. Benzene exceeded remediation levels and a NOV was issued. Benzene levels were >100 in the soil. Mr. L.C. Pettaway is deceased and his widow says she does not have the financial resources to remediate site. The current status of the site is "inabled" financially (IFIN). Mr. Pierce said ADEM does not have Trust Fund money available to remediate the site so remediation will not occur until funds become available.

INSPECTOR'S NAME: _____

DATE INSPECTED: _____

SUPERVISOR'S SIGNATURE: _____

HAZARDOUS MATERIALS NOTIFICATION FORM

PROJECT #: NCPD-PE02(910) STATION/SITE: E

MUNICIPALITY OR COMMUNITY: Montgomery COUNTY: Montgomery

FACILITY NAME: Scott's Trailer Wash

FACILITY ADDRESS: 8500 Selma Hwy 80

Montgomery, AL 36108

OWNER'S NAME: Scott Holcomb

OWNER'S ADDRESS: Pollard St.

Fort Deposit, AL 36032

FACILITY PHONE #: (334)-227-0006 OWNER'S PHONE #: (334)-227-0006

ADEM REGISTRATION #: _____

TYPE OF FACILITY [check applicable response(s)]:

- Gas Station
- Dry Cleaner
- Fertilizer Plant
- Plating Plant
- Leather Tannery
- Scrap Metal
- Chemical Plant
- Wood Treating Plant
- Auto Parts w/Engine Repair Shop
- Foundry
- Manufacturing Facility
- Farmer's Cooperative
- Landfill
- Other (Specify): Trailer Wash

COMMENTS: One AST containing gasoline was noted at 8500 Hwy 80, west of the Montgomery near the airport.

INSPECTOR'S NAME: Jerald Overstreet/Thomas Lee

DATE INSPECTED: June 12, 2006

SUPERVISOR'S SIGNATURE: _____



Photo 1: View of sign at Scott' Trailer Wash located at 8500 Selma Hwy 80.



Photo 2: AST located at Scott's Trailer Wash



Photo 3: View of the building at Scott's Trailer Wash.